



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	15	<b>Date:</b>	8/11/2004	<b>MeterBasin:</b>	01_WR12
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5713		Oakshire	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 13

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0811-2004\T-1\PLAYER\_A(A)2004\_0811Image0013.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

15

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\15.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	16	<b>Date:</b>	8/11/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2203		Arden	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 14

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0811-2004\T-1\PLAYER\_A(A)2004\_0811Image0014.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

16

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\16.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	16	<b>Date:</b>	8/11/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2205		Arden	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 15

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0811-2004\T-1\PLAYER\_A(A)2004\_0811Image0015.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

16

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\16.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	16	<b>Date:</b>	8/11/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2205		Arden	ROAD

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	75	

**Comments:** smoke from ground

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 16

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0811-2004\T-1\PLAYER\_A(A)2004\_0811Image0016.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

16

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\16.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	16	<b>Date:</b>	8/11/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2200		Arden	ROAD

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	

**Comments:** smoke from grass

## SMOKE TEST PHOTOS



**Photo No:** 13

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0811-2004\T-1\PLAYER\_B(B)2004\_0811Image0013.JPG

**Image Status:** Image found and displayed.



**Photo No:** 14

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0811-2004\T-1\PLAYER\_B(B)2004\_0811Image0014.JPG

**Image Status:** Image found and displayed.



**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Retakes\UTID16-B1\_2005\_0523Image003.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

16

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\16.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	17	<b>Date:</b>	8/11/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5734		Ridgedale	ROAD

<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	12=Alley	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	200	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 17

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0811-2004\T-1\PLAYER\_A(A)2004\_0811Image0017.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

17

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\17.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

<b>Unique Test ID</b>	17	<b>Date:</b>	8/11/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	0	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
---------------------	-----------------------	---------------------	---------------------

<b>Source Type:</b>	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	<b>Drainage Area:</b> 0	
<b>Comments:</b> No defects observed		

---

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

17

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\17.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	18	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5750		Cross Country	Blvd
<b>Source Type:</b>	18= Other	<b>Location:</b>	5=Sidewalk
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	250
<b>Comments:</b>	hole in sidewalk		

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 12

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0012.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

18

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\18.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	18	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2200		Crest	ROAD

<b>Source Type:</b>	18= Other	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	250	
<b>Comments:</b>	hole in sidewalk			

## SMOKE TEST PHOTOS



**Photo No:** 13

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0013.JPG

**Image Status:** Image found and displayed.



**Photo No:** 14

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0014.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

18

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\18.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	18	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2200		Crest	ROAD

<b>Source Type:</b>	18= Other	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0
<b>Comments:</b>	by sanitary sewer		

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 15

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0015.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

18

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\18.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	18	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5750		Cross Country	Blvd

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
---------------------	--------------	------------------	--------------	------------------

<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0
----------------	-----------	-----------------------	---

**Comments:** Clean-out

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 11

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_B\B\_2004\_0812Image0011.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

18

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\18.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	18	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5800		Cross Country	Blvd

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	11=Field	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	200	

**Comments:** Hole in ground

## SMOKE TEST PHOTOS




**Photo No:** 12

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_B\B\_2004\_0812Image0012.JPG

**Image Status:** Image found and displayed.



**Photo No:** 13

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_B\B\_2004\_0812Image0013.JPG

**Image Status:** Image found and displayed.



**Photo No:** 10

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID18-B2\2005\_0523Image010.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

18

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\18.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	19	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2210		Crest	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	60	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 1

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0001.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

19

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\19.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	19	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	2	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2208		Crest	ROAD

<b>Source Type:</b>	14= Catch Basin	<b>Location:</b>	6=Curb	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	4500	

**Comments:** inlet

## SMOKE TEST PHOTOS



**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0002.JPG

**Image Status:** Image found and displayed.



**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0003.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

19

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\19.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	19	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2214		Crest	ROAD

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	50	

**Comments:** water meter

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 4

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0004.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

19

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\19.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


<b>Unique Test ID</b>	19	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2214		Crest	ROAD

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	25	

**Comments:** sidewalk

## SMOKE TEST PHOTOS



**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0005.JPG

**Image Status:** Image found and displayed.



**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Retakes\UTID19-A4\_2005\_0523Image008.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

19

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\19.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	19	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2218		Crest	ROAD

<b>Source Type:</b>	18= Other	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	150	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 6

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0006.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

19

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\19.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY


Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	19	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	6	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2218		Crest	ROAD

<b>Source Type:</b>	18= Other	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	200	
<b>Comments:</b>	front yard hole			

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0008.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

19

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\19.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	19	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	7	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2218		Crest	ROAD

<b>Source Type:</b>	18= Other	<b>Location:</b>	6=Curb	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	75	
<b>Comments:</b>	curb drain			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 7

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0007.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

19

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\19.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	19	<b>Date:</b>	8/12/2004	<b>MeterBasin:</b>	01_WR10
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	8	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2206		Crest	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	
<b>Comments:</b>	front yard			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 9

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0812-2004\T-1\PLAYER\_A\A\_2004\_0812Image0009.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

19

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\19.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.